





# Ramses 2.3 Release Notes

## Updates

Please check our Web site http://www.merging.com periodically for information, patches and updates.

Thank you for your feedback which is very useful to us to develop and improve the best products for your needs.

The Merging Technologies team

## Installation

Please consult the Ramses Upgrade 1.04a guide under <u>http://www.merging.com/ramses/download</u> Make sure that there will be no electrical cuts during a firmware upgrade; if not sure please connect Ramses onto a UPS.

#### Install following versions:

### **Pyramix**

Pyramix version - Pyramix Virtual Studio V6.1.17 MR1Build772

Downloadable from: http://www.merging.com/download

### <u>Ramses</u>

- Ramses firmware <u>Consolefirm 2.3.5.12 2009.09.29 .bin</u>
- Ramses consolesoft <u>Consolesoft 2.3.5.2300 2009.08.25 Ramses .zip</u>
- Optional) Edit bay key set Consolesoft Set9 2008.03.19 1400.rms

Downloadable from: <u>http://www.merging.com/ramses/download</u> or <u>http://www.smartav.net/smartconsoles/downloads.php#Pyram</u>





## **NEW FEATURES**

• HUI support for ProTools (Mac version only) control

## **IMPROVEMENTS**

- Automation modes consistency improved.
- OASIS communication efficiency improved.
- Fader move sensibility improved before sending the automation touch.
- Packed .ecf .mcf .gcf .tcf into project save

**BUG FIXES** (some fixed bugs could be missing from the list)

- Fixed Level Meter 0.5 dB offset
- Aux sends mapping better match the Pyramix Aux button.
- Ramses groups are correctly saved/reload between projects.
- Auto Show plug-in window option can change strip tools parameters. Fixed. Also fix in Pyramix 6.0 MR and Pyramix 6.1
- Inplace button correctly mapped to the inplace/center monitor panel function.
- Dedicated EQ/Dynamics controls are working correctly now.
- Stereo Panning On/Off state mismatches issues.

